
Appendix I. Deepwater Horizon Investigation Fault Trees


Appendix la. Well integrity was not established or failed

Appendix Ib. Hydrocarbons entered the well undetected and well control was lost


Appendix Ic. Hydrocarbons ignited on *Deepwater Horizon*

Appendix Id. The blowout preventer did not seal the well






Each box describes a matter that the investigation team identified as a possible contributing factor, and, where applicable, indicates whether the hypothesis in the box was to be examined as a "Possible Immediate Cause" or "Possible System Cause". References to sections are to the sections in the *Deepwater Horizon* Accident Investigation Report where the team's analysis and conclusions can be found.



CRITICAL FACTOR THE BLOWOUT PREVENTER DID NOT SEAL THE WELL



Each box describes a matter that the investigation team identified as a possible contributing factor, and, where applicable, indicates whether the hypothesis in the box was to be examined as a "Possible Immediate Cause" or "Possible System Cause". References to sections are to the sections in the *Deepwater Horizon* Accident Investigation Report where the team's analysis and conclusions can be found.